


# Brunswick Computer Lane Monitor™ Lane Dressing Analysis System

	Center Name	Lane #	Distance	Date	Comment
1	DOMMS	10	25.0	11/23/2011	
2	DOMMS	10	15.0	11/23/2011	
3	DOMMS	10	35.0	11/23/2011	

	1	2	3
IL2	5.5	2.1	3.2
IL3	5.0	4.3	2.5
IL4	5.7	5.5	1.8
IL5	5.9	5.8	2.2
IL6	10.2	5.3	2.3
IL7	15.5	7.5	3.3
IL8	15.2	14.9	5.9
IL9	21.5	19.6	6.1
L10	36.0	34.5	8.9
L11	45.0	58.8	11.8
L12	53.4	60.5	17.3
L13	55.1	64.9	19.3
L14	57.0	72.5	19.0
L15	59.9	65.6	18.2
L16	55.5	69.5	17.6
L17	61.1	66.8	19.2
L18	58.0	69.1	17.6
L19	53.8	68.1	17.6
C20	63.2	69.0	19.8
R19	61.3	73.5	20.5
R18	59.4	73.3	19.6
R17	60.8	74.8	19.4
R16	59.5	72.6	18.5
R15	60.2	69.4	20.0
R14	59.4	71.2	20.9
R13	61.9	71.5	20.1
R12	56.6	72.6	18.6
R11	49.0	70.8	20.7
R10	37.4	67.4	17.2
R9	22.5	62.8	13.5
R8	14.9	41.3	9.1
R7	10.6	24.6	6.4
R6	6.9	15.2	4.8
R5	5.7	8.1	3.1
R4	4.8	6.0	2.5
R3	4.6	5.3	2.2
R2	5.0	5.5	1.8



First Tape Reading  
10 Pin Side

7 Pin Side